

00200804

~~14~~ ~~14~~ ~~RAGS~~  
1a 14 Rags

12  
273  
12  
146  
546  
273  
3276



27 MAR 1998

Form approved, OMB No. 2050-0039, expires 09-30-91

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C.A.D.0.8.6.5.1.0.0.0.5		Manifest Document No. 91728		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address McDonnell Douglas Aircraft Co. 19503 S. Normandie Ave., Torrance, CA 90502						A. State Manifest Document Number No 00200804			
4. Generator's Phone (213) 533-6677						B. State Generator's ID 99906			
5. Transporter 1 Company Name Nash Salvage, Inc.						C. State Transporter's ID TDWR# 41028			
6. US EPA ID Number C.A.D.9.9.0.8.0.2.9.9.3						D. Transporter's Phone (213) 946-8431			
7. Transporter 2 Company Name						E. State Transporter's ID			
8. US EPA ID Number						F. Transporter's Phone			
9. Designated Facility Name and Site Address Chemical Waste Management Hwy. 73 Port Arthur, Texas 77643						G. State Facility's ID HW 50212-001			
10. US EPA ID Number T.X.D.0.0.0.8.3.8.8.9.6						H. Facility's Phone (409) 736-2821			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)					12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	1. Waste No.
	a. "RQ" Hazardous Waste Solid, N.O.S. <del>(F002)</del> , ORM-E, NA 9189 (F001, F003, F005)					0.0.1	C.M.	Y	980790 <del>980790</del> F001, F003, F005
	b.								
	c.								
	d.								
J. Additional Descriptions for Materials Listed Above Rags contaminated with solvent.						K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Gloves & Goggles						CWM PAI K07667061, WO #900328008			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name Kris L. Anderson						Signature <i>[Signature]</i>		Month Day Year 03/19/90	
17. Transporter 1 Acknowledgement of Receipt of Materials						TR# 9528		Date	
Printed/Typed Name FRANCISCO COSS						Signature <i>[Signature]</i>		Month Day Year 03/19/90	
18. Transporter 2 Acknowledgement of Receipt of Materials								Date	
Printed/Typed Name						Signature		Month Day Year	
19. Discrepancy Indication Space Sector 1a, 13a, 1a Were corrected prior to the arrival at CWM-PTA LTD									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name LAM DAN L						Signature <i>[Signature]</i>		Month Day Year 03/28/90	

**REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)**

**INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)**

- (1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.
- (2) Enter the total number of pages used to complete this manifest.
- (3) Enter the company name and mailing address.
- (4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.
- (5) Enter the company name of the first transporter and their U.S. EPA ID Number.
- (6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).
- (7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.
- (8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**
- (9) Complete the waste description table as follows:
  - (A) **ITEM 11A** - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.
  - (B) **ITEM 11** - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.
  - (C) **ITEM 12** - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.
  - (D) **ITEM 13** - Enter the total quantity of waste described on each line.
  - (E) **ITEM 14** - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	
  - (F) **ITEM 1** - Enter the appropriate TWC State Waste Code for each waste you are shipping.
- (10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.
- (11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.
- (12) Generator retains green copy, sending remaining copies with the driver.

**INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)**

- (1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.
- (2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.
- (3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".
- (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the TSD Facility Owner/Operator.

**INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)**

- (1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.
- (2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.
- (3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

\* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW, Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No. 97728	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address McDonnell Douglas Aircraft Co. 19503 S. Normandie Ave., Torrance, CA 90502 4. Generator's Phone (213) 533-6677				A. State Manifest Document Number ND 00200804			
5. Transporter 1 Company Name Nash Salvage, Inc.				B. State Generator's ID 99906			
6. US EPA ID Number C A D 9 9 0 8 0 2 9 9 3				C. State Transporter's ID TDWR# 41028			
7. Transporter 2 Company Name				D. Transporter's Phone (213) 946-8431			
8. US EPA ID Number				E. State Transporter's ID			
9. Designated Facility Name and Site Address Chemical Waste Management Hwy. 73 Port Arthur, Texas 77643				F. Transporter's Phone			
10. US EPA ID Number T X D 0 0 0 8 3 8 8 9 6				G. State Facility's ID HW 50212-001			
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)				H. Facility's Phone (409) 736-2821			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No.	13. Total Quantity	14. Unit Wt./Vol	15. Waste No.
	a. "RQ" Hazardous Waste Solid, N.O.S. (F002), ORM-E, NA 9189 (F001, F003, F005)			0 0 1 C M	12	Y	980790 F001, F003, F005
	b.						
	c.						
	d.						
J. Additional Descriptions for Materials Listed Above Rags contaminated with solvent.				K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Gloves & Goggles				CWM PAI K07667061 WO #90032201			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name Kris C. Anderson				Signature [Signature]		Month Day Year 03/19/90	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature TR# 9538		Date	
Printed/Typed Name Francisco Coss				Signature Francisco Coss		Month Day Year 03/19/90	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Month Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name				Signature		Month Day Year	

EPA ID #TXD000838896  
TX ID #HW-50212-001



Chemical Waste Management  
Port Arthur Treatment Complex

000017

## Certificate of Destruction

Chemical Waste Management has incinerated waste received from Douglas A/c as identified in hazardous Waste Manifest # 200804 at it's Port Arthur, Texas treatment complex and hereby certifies such destruction as of this 9th day of April 19 90.

Generator Douglas A/c  
Address 19685 S. Normandy  
Torrance, Ca. 90502  
Contact Kris Anderson

By Sharon Kille  
Title Receiving Coordinator